

S.S.C. Radisson Diamond.

USPH Inspection Violations and Corrective Actions.

Periodic Inspection held 19 November 2003 in San Juan.
Score 97 points.

No.	Ref.	Pts.	Critical.	Violation.	Corrective Actions.
1	8	0	No.	Potable Water. The potable water production halogenation records for April 2003 through August 2003 were not available for inspection. These records were located after the inspection was complete and were shown to the inspector as the inspector was leaving the ship.	Missing record located at time of inspection.
2	19	2	No.	Main Galley. Three soiled coffee ground holders were stored at the hand wash station. Coffee grinds were noted at the hand wash station when washing of hands was initiated. The holders were immediately removed from the area.	Coffee ground holders removed at time of inspection. Crew instructed not to place items at hand wash stations.
3	21	0	No.	Main Galley. Two external temperature gauges on the combi ovens were not working and the cover pieces were missing.	Gauges replaced with new. Cover pieces replaced.
4	21	“	No.	Grill Galley. An open seam on the ventilation hood was noted, making cleaning difficult. The seam was sealed immediately.	Seam sealed with approved sealant at time of inspection.
5	22	0	No.	Main Galley. The pressure gauges on the ware washer and glass washer were 8 and 5 PSI above the manufacturer's recommended range. The gauges were adjusted immediately.	Gauges adjusted at time of inspection.
6	33	1	No.	Main Galley. The grouting around the tiles in the hot grill area was recessed making cleaning difficult.	Tile grouting to be replaced at next refit.
7	33	“	No.	Crew Galley. The grouting around tiles was recessed making cleaning difficult.	Tile grouting to be replaced at next refit.
8	37	0	No.	Main Galley – Ware washer. Heavy condensation was noted on the deckhead over the soiled end of the ware washer.	Ventilation to area improved to eliminate condensation.